

PHOTOGRAPHS OF STRUCTURES IN 500 FOOT BUFFERS



Photograph 1. Structure 1, 28 Wells Avenue. This concrete structure was formerly part of the Otis Elevator complex, and was constructed in the early 20th century.



Photograph 2. Structure 4, 5 Buena Vista Avenue. The Metro North and Amtrak train station, constructed in 1911 from designs by Warren & Wetmore, architects of Grand Central Terminal in New York City.



Photograph 3. Structure 5, [26] Wells Avenue. This four-story concrete structure was formerly occupied by the Otis Elevator company, and was constructed in the early 20th century.



Photograph 4. Structure 6, [31] Wells Avenue. This concrete and masonry structure was formerly one of the buildings which housed the Otis Elevator company, and was constructed in the early 20th century.



Photograph 5. Structure 8, [43] Dock Street. This art deco office building dates to the second quarter of the 20th century.



Photograph 6. Structure 9, 39-41 Dock Street. This pair of one-story commercial structures dates to the early 20th century.



Photograph 7. Structure 10, 2 Bashford Street. This three-story brick commercial and residential structure dates to c.1875.



Photograph 8. Structure 11, 4 Bashford Street. This three-story masonry structure dates to c.1900 and was formerly the site of the business of M. J. Cantwell.



Photograph 9. Structure 12, [28] Bashford Street. A five-story brick masonry industrial structure, constructed c.1890.



Photograph 10. Structure 13, [11] Woodworth Avenue. This five-story masonry structure is one of the earlier surviving structures formerly associated with the Otis Elevator company, and dates to c.1885.



Photograph 11. Structure 14, 9 Woodworth Avenue. This three-story stable constructed of brick still retains its late 19th or early 20th century signage.



Photograph 12. Structure 15, 5-7 Woodward Avenue. This three-story masonry structure, apparently formerly the site of a discount clothing store, retains painted signage from the mid 20th century.



Photograph 13. Structure 18, 29 Warburton Avenue. Philipse Manor Hall. Constructed initially during the late 17th century and with substantial additions up to the mid 19th century, this masonry structure is listed on the National Register of Historic Places and is a National Historic Landmark.



Photograph 14. Structure 19, 64-66 Warburton Avenue. A two-story masonry commercial structure with expansive areas of glass and iron and pressed tin façade, dating to c.1900.



Photograph 15. Structure 20, 62 Warburton Avenue. This four-story mixed-use structure dates to the last quarter of the 19th century.



Photograph 16. Structure 21, 7 Wells Avenue. A three-story masonry structure, dating to c.1900.



Photograph 17. Structure 22, [5] Wells Avenue. This four-story mixed-use masonry structure was initially constructed as a three-story building during the 19th century, and received a fourth floor c.1900.



Photograph 18. Structure 23, 73 North Broadway. This three story brick dwelling was constructed during the last quarter of the 19th century.



Photograph 19. Structure 26, 6-8 Wells Avenue. This two story neoclassical style brick commercial structure was constructed c.1900.



Photograph 20. Structure 27, 56 Warburton Avenue. A two-story brick mixed-use structure dating to the last quarter of the 19th century.



Photograph 21. Structure 28, 50 Warburton Avenue. A four-story brick mixed-use structure, constructed c.1900.



Photograph 22. Structure 29, 48 Warburton Avenue. A three-story mixed-use brick masonry structure, constructed c. 1890.



Photograph 23. Structure 30, 46 Warburton Avenue. A three-story brick masonry mixed-use building, constructed c. 1890.



Photograph 24. Structure 33, 40 Warburton Avenue. A three-story brick masonry mixed-use building, dating to the last quarter of the 19th century.



Photograph 25. Structure 34, 38 Warburton Avenue. A three-story wood-framed mixed-use building, constructed c. 1870.



Photograph 26. Structure 35, 36 Warburton Avenue. A three-story brick mixed-use structure, constructed during the last quarter of the 19th century.



Photograph 27. Structure 37, 11 Manor House Square. A three-story brick mixed-use structure, dating to c. 1890.



Photograph 28. Structure 38, 9 Manor House Square. A three-story brick mixed-use structure, dating to c. 1900.



Photograph 29. Structure 39, 5 Manor House Square. A two-story brick mixed-use structure, constructed c. 1900.



Photograph 30. Structure 44, 2 Manor House Square. A four-story brick mixed-use structure, constructed c. 1890, with c.1930 glass paneled Art Deco commercial front.



Photograph 31. Structure 45, 31-33 North Broadway. A four-story brick mixed-use building with cast iron, constructed c. 1890.



Photograph 32. Structure 48, 36-38 North Broadway. A two-story mixed-use structure dating to the first quarter of the 20th Century.



Photograph 33. Structure 49, 42-48 North Broadway. A three-story mixed-use structure, with metal front, dating to c.1935.



Photograph 34. Structure 50, 1 Manor House Square. A one-story bank building with intact storefront, constructed c. 1940.



Photograph 35. Structure 51, 47 North Broadway. A four-story brick masonry residence, constructed c.1840 with later alteration of the first floor to a storefront.



Photograph 36. Structure 52, 50 North Broadway. A two-story brick mixed-use building, constructed during the second half of the 19th century.



Photograph 37. Structure 53, 52 North Broadway. A three-story brick mixed-use building, constructed c. 1900.



Photograph 38. Structures 54 and 56, 54 and 56 North Broadway. These three-story brick mixed-use structures with pressed metal detailing were constructed c.1900.



Photograph 39. Structure 57, 58 North Broadway. A two-story brick mixed-use structure, constructed in the early 19th century with early 20th century alterations.



Photograph 40. Structure 58, 62-64 North Broadway. A three-story brick masonry residence with Italianate details, constructed c.1870.



Photograph 41. Structure 59, 66 North Broadway. A four-story brick mixed-use structure with slate roof and elaborate decorative brickwork, constructed c.1890.



Photograph 42. Structure 60, 25 Overlook Terrace. A pair of five-story brick apartment buildings, dating to the c.1925.



Photograph 43. Structure 61, 10 Baldwin Place. A two-story wood-framed upright-and-wing house, constructed c.1850.



Photograph 44. Structure 62, 15 Overlook Terrace. A four-story brick apartment building, probably constructed during the first quarter of the 20th century.



Photograph 45. Structure 64, 18 Baldwin Place. A two-story brick house with a three-story tower and pedimented gables, constructed during the last quarter of the 19th century.



Photograph 46. Structure 65, 2 Bell Place. A two-story wood-framed house with dentil molding and Italianate brackets on the cornice, constructed during the last quarter of the 19th century.



Photograph 47. Structure 69, 14 Locust Hill Avenue. A four-story brick apartment building with decorative brickwork, constructed c. 1920.



Photograph 48. Structures 70, 71 and 72; 16, 18, and 20 Locust Hill Avenue. Four-story brick apartment buildings with decorative brickwork, constructed c. 1920.



Photograph 49. Structure 74, 39 Locust Hill Avenue. A 1½-story wood-framed cottage with a mansard roof, constructed c. 1875.



Photograph 50. Structure 75, 30 Locust Hill Avenue, Locust Hill Garden Apartments. A seven-story brick apartment building on a stone foundation, constructed c. 1930.



Photograph 51. Structure 76, 45 Locust Hill Avenue. A three-story brick masonry house with Queen Anne and gothic detailing, constructed c. 1890.



Photograph 52. Structure 77, 53 Locust Hill Avenue. A two-story house constructed of brick and wood frame in the Queen Anne style, dating to c.1890.



Photograph 53. Structures 75, 78 and 80; 30, 40 and 50 Locust Hill Avenue. Locust Hill Garden Apartments. These seven-story brick apartment buildings on stone foundations were constructed c. 1930.



Photograph 54. Structure 79. 57 Locust Hill Avenue. A two-story brick house with decorative brickwork, constructed c. 1870.



Photograph 55. Structure 105, Building 5 Schroeder Street, at right. An eight-story brick apartment building, constructed c. 1940. Structure 109, Building 9 Schroeder Street, is seen in the background at center.



Photograph 56. Structure 106, Building 6 Schroeder Street. An eight-story brick apartment building, constructed c. 1940.



Photograph 57. Structure 107, Building 7 Schroeder Street. An eight-story brick apartment building, constructed c. 1940.



Photograph 58. Structure 108, Building 8 Schroeder Street. An eight-story brick apartment building, constructed c. 1940.



Photograph 59. Structure 109, Building 9 Schroeder Street, at left. An eight-story brick apartment building, constructed c. 1940. See photograph 54 for another view of this structure.